



SURVEY FOR DENNIS AND ELIZABETH BRUNS

152910003



LEGEND

- Iron Pin Found
- Iron Pin Set
- ⊙ Mag Nail Set
- ⊗ Mag Nail Found




Basis of Bearings

The east line of the northwest quarter of Section 29, having a bearing of S00°00'00"W.

N/A
Zoning Inspector

Surveyed By:
Craig W. Mescher Reg. Surveyor No. 8237

References:
Mercer County Local Coordinate Datum
All Deeds of Record



Part of NW 1/4 Sec. 29 Town 13N Range 3E
Township: Granville Village: _____
County: Mercer
State: Ohio Date: May 2, 2012

15-6(29)